

Carl Bauer <carl.bauer@broadarrowgroup.com>

Build Documents Request AM115 744 1969 Maserati Ghibli

FABIO COLLINA <fabio.collina@maserati.com> To: Carl Bauer <carl.bauer@broadarrowgroup.com>

Mon, Jul 4, 2022 at 12:56 AM

Dear Mr. Bauer,

thanks for your kind email, you are welcome!

Please find below basic information about the car, I hope it could be useful.

Basic information:	GHIBLI Coupè (AM115)
Chassis number	AM115*0744*
Model	GHIBLI Coupé (AM115)
Body	GHIA (Giugiaro design) - Closed
Displacement	4.719 cm3 - Carburettors
Gearbox type	Manual type ZF S 5/325
External colour	"Verde Acqua" (Metallic Green)
Interiors leather colour	"Senape" (Tan)

Date of production	27/11/1968
Right hand drive	No
Delivery area	Munich - Germany

Regarding the Historical Documentation Service, I would like to inform you that in order to start the procedure we kindly need to receive from you pictures of the car (exterior/interior), pictures of the identification labels and (important) the picture of the chassis number stamped on the frame and of the engine number and engine internal number stamped on the engine block. Please refer to the attachments to easily find the requested numbers.

Once received ALL the requested pictures, I'll be able to check in our Historical Archive about the availability of historical documents for your car (please confirm the ownership of the vehicle, thanks).

After the research I'll advise you about the documents available for your car, their contents and prices. The research is totally free of charge.

IMPORTANT NOTE: please kindly be advised that in few days I'll be on vacation until next 27th July. Please be so kind to send me the requested pictures after that date, many thanks for your kind understanding!

My best regards and happy motoring

Fabio Collina

Fabio Collina

Archivio Storico Maserati S.p.A.



Invoice

Date	Invoice #
8/14/2017	175446

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149

Year, Make, Model

1969 Maserati Ghibli 4.7 Coupe Vin# AM115744 Lic# HX86207 (NY)

Mileage Terms

005,087

Quantity	Item Description	Rate	Amount
1 spord	45899 O Ring	1.46	1.4
1 spord	68571 Oil Return Hose	42.88	42.88
1 spord	66185 Condenser Distributor	14.92	14.92
1 spord	66182 Distributor Points Set	58.41	58.4
1 spord	49441 Axle Rod Support Mount	102.00	102.00
6 spord	50621040 Bushing	35.33	211.98
4 spord	48197 Lower Control Arm Bushing	11.25	45.0
4 spord	48190 Upper Control Arm Bushing	11.25	45.00
2 spord	48196 Fulcrum Shaft Lower A Arm	121.76	243.5
2 spord	67069 Upper Ball Joint	44.95	89.90
4 spord	34748 Bushing Silent Block	31.40	125.6
6 spord	44118 Stabilizer Bar Bushing	25.36	152.10
4 spord	47969 Bushing Leaf Spring End	46.20	184.8
. 2 spord	56199 Steering Link Rod Assembly	114.00	228.0
8 spord	58835 Stabilzer End Link Bushing	5.44	43.5
3 spord	48345 Brake Hose	39.51	118.5
2 spord	42573 Bushing Silent Block	44.18	88.3
4 spord	57214 Bush Front Shock Absorber	95.00	380.0
2 spord	52764 Rear Shock Grommet Set	18.92	37.8
1 spord	00448 Power Steering Pump Seal Kit	79.81	79.8
1 spord	65987 Parking Brake Pads	87.50	87.5
4 spord	Weber DCNL Carburetor Repair Kit	98.95	395.8
1 spord	2311300 Oil Filter	29.50	29.5
8 spord	727401 Spark Plug Boot	2.34	18.7
1 Sublet	Flush and Test AC Condenser	275.00	275.0
1 spord	FHM 7.5x3 Fuel Hose	48.78	48.7
1 spord	4L300W Belt	17.54	17.5
2 spord	4L390W Belt	20.94	41.8
1 spord	765-3509 A/C Pag Lubricant	16.94	16.9
12 20w-50	Mobil Motor Oil	8.58	102.9
3 ATF	ATF Hydraulic Fluid	7.25	21.7
2 gal	Antifreeze	21.99	43.9
17.828 Fuel/ga		2.899	51.6

Sales Tax (6.35%)

Total

Tel: 203-327-1747 Fax: 203-327-7140

www.vantagemotorsports.com



Invoice

Date	Invoice #
8/14/2017	175446

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149

Year, Make, Model

1969 Maserati Ghibli 4.7 Coupe Vin# AM115744 Lic# HX86207 (NY)

Mileage Terms

005,087

3 LMA-GTQ Castrol DOT 4 Brake Fluid LMA 17.69 8 Paint/Materials DE1635 Semi Gloss Black Paint 11.80 1 spord 513929 Brown Paint 9.49 1 spord 214152 Pt 2 x GLS 8.45 1 spord 165241 1/8 x 3/4 x 48 ZC Angle 17.99 1 spord 713131 Cable Ground 40.70 1 Alignment Perform Wheel Alignment 165.00 1 spord GRW125 Washer Pump 34.81 1 misc/hardware Adjustable Clutch Master Cylinder Rod 11.75 1.5 misc/hardware Weather Strip Window Run Channel 7.00 42 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorbers bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends. Remove and replace steering tie rods & tie rod ends. Remove and replace front and rear brake hoses. Bleed	lmount	Rate	Description	ltem	Quantity
1 spord 1 spord 2 spord 2 spord 2 spord 3 spord 3 spord 4 spord 5 spord 5 spord 5 spord 5 spord 6 spord 6 spord 7 spord 7 spord 7 spord 6 spord 6 spord 7 spord 7 spord 7 spord 6 spor	53.07		Castrol DOT 4 Brake Fluid LMA	LMA-GTQ	3
1 spord 1 spor	94.40		DE1635 Semi Gloss Black Paint	Paint/Materials	8
1 spord 1 spord 1 spord 1 spord 7 spord 7 spord 7 spord 7 spord 7 spord 1 Alignment Perform Wheel Alignment 165.00 1 spord 1 spord GRW125 Washer Pump 34.81 1 misc/hardware Adjustable Clutch Master Cylinder Rod 11.75 1.5 misc/hardware Weather Strip Window Run Channel 7 cod 42 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	9.49		513929 Brown Paint	spord	1
1 spord 713131 Cable Ground 40.70 1 Alignment Perform Wheel Alignment 165.00 1 spord GRW125 Washer Pump 34.81 1 misc/hardware Adjustable Clutch Master Cylinder Rod 11.75 1.5 misc/hardware Weather Strip Window Run Channel 7.00 42 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	8.45			spord	1
1 Alignment Perform Wheel Alignment 165.00 1 spord GRW125 Washer Pump 34.81 1 misc/hardware Adjustable Clutch Master Cylinder Rod 11.75 1.5 misc/hardware Weather Strip Window Run Channel 7.00 42 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	17.99			spord	1
1 spord GRW125 Washer Pump 34.81 1 misc/hardware Adjustable Clutch Master Cylinder Rod 11.75 1.5 misc/hardware Weather Strip Window Run Channel 7.00 42 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	40.70		20명의 XX 전략 10명의 전략 10명의 10명의 10명의 10명의 10명의 10명의 10명의 10명의		1
1 misc/hardware 1.5 misc/hardware 2 Labor/Hour 3 Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorbers bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	165.00				1
1.5 misc/hardware Weather Strip Window Run Channel 7.00 Labor/Hour Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	34.81		[전통] (1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	그래마 가지겠었는데 그 그는 없는데 그는 다음을 하고 있다.	1
Dissassemble and overhaul front suspension. Prepare and refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	11.75		에 얼마들은 사람이 많아 아이지 않는데 아이지를 하면 하면 가장 아이를 하면 하면 하는데		
refinish front control arms, springs, shock absorbers, sway bars & hardware. Remove and replace front control arm bushings. Overhaul lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	10.50	7.00	Weather Strip Window Run Channel	misc/hardware	1.5
lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.	5,250.00	125.00	refinish front control arms, springs, shock absorbers, sway	Labor/Hour	42
lower ball joints. Replace upper ball joints. Assemble front suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.			보고 있는데 전 3000 THE		
suspension with new sway bar bushings, control arm bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.					
bushings etc. Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.					
Replace front and rear shock absorber bushings. Refinish front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.			- ^ ^ 마른 사는 사용에서 바로 마른 아이들은 아이들은 아이들의 아이들의 아이들의 아이들의 아이들의 아이들의 아이들의 아이들의		
front and rear shock absorbers. Clean front wheel bearings and repack with new grease. Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.					
Refit hubs to spindles and adjust wheel bearings. Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.			front and rear shock absorbers.		
Overhaul rear suspension. Remove and replace leaf spring & shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.			Clean front wheel bearings and repack with new grease.		
& shackle bushings. Remove and replace differential torque rod bushings. Remove and replace steering tie rods & tie rod ends.					
torque rod bushings. Remove and replace steering tie rods & tie rod ends.					
Remove and replace steering tie rods & tie rod ends.					
Remove and replace front and rear brake hoses, Bleed					
brake and clutch hydraulics with new fluid.					
Remove distributor cap to replace igntion points and			도" 그리면 없었다면서 12 10 10 10 10 10 10 10 10 10 10 10 10 10		
condenser. Set points gap to spec and assemble			를 가는 선생님들은 점점 인터를 통해 전에 계속을 하면 되었다. 그는 그래도 하는데 이번 이번 경험 전에 되었다면 보고 있다면 보고 있다면 사람이 되었다면 하는데 이번 경험에 되었다면 되었다면 되었다면 하는데 보고 있다면 보고 있다면 되었다면 되었다면 보고 있다면 되었다면 되었다면 보고 있다면 보고 있다		
distributor.			a THOUSENSE TO A TOTAL CONTROL CONTRO		
Remove spark plugs, clean & set diode gaps. Install new spark plug wire terminal boots as existing ones were dry					

Sales Tax (6.35%)

Total

Tel: 203-327-1747 Fax: 203-327-7140 www.vantagemotorsports.com



Invoice

Invoice # Date 175446 8/14/2017

Stamford, CT 06907

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149

Year, Make, Model

1969 Maserati Ghibli 4.7 Coupe Vin# AM115744 Lic# HX86207 (NY)

> Terms Mileage

005,087

Quantity	ltem	Description	Rate	Amount
		and cracked.		
		Remove all four carburetors, disassemble and overhaul		
		carburetors.		
		Replace all fuel hoses in engine compartment. Remove power steering pump and rebuild (leaking fluid).		
		Replace all v belts.		
		Remove a/c condenser and sublet ot be cleaned and		
		tested.		
		Remove oil tank and clean sludge out of tank. Refinish oil		
		tank.		
		Remove and replace oil tank return hose, remove return		
		hose flange from engine and replace o ring (leaking engine		
		oil). Replace oil filter and top up engine with new oil.		
		Replace battery ground cable. Fabricate and install battery		
		securing bracket (bracket was missing & battery was		
		loose).		
		Evacuate and recharge A/C system.		
		Check all lights, wipers, washer, fan etc. Repair head lamps		
		(not working).		
		Diagnose and repair windshield washer. Remove and replace faulty washer pump. Install correct style washer		
		pump switch to dash (no charge for switch as it was a used		
		unit).		
		Run engine and synchronize carburetor idles and throttles.		
		Adjust carburetor mixtures.		
		Remove fixed clutch master cylinder rod and install		
		adjustable type to level clutch pedal with brake pedal. (As		
		it was the clutch pedal was approximately 1" lower than the brake pedal.		
		Secure loose windshield molding (was coming out of the		
		rubber by the windshield wipers).		
		Secure and glue door window run channels to passenger		
		secure and give door window run charmers to passenger		

Sales Tax (6.35%)

Total

Tel: 203-327-1747 Fax: 203-327-7140

www.vantagemotorsports.com



Stamford, CT 06907

Invoice

Date

Invoice #

8/14/2017

175446

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149

Year, Make, Model

1969 Maserati Ghibli 4.7 Coupe Vin# AM115744 Lic# HX86207 (NY)

Mileage

Terms

005,087

Quantity

Description

Rate

Amount

and driver side doors. (falling out). Install new driver door window run channel (top) as it was missing entirely. Test drive vehicle. Wash and clean.

Sales Tax (6.35%)

\$580.51


Tel: 203-327-1747

Fax: 203-327-7140

www.vantagemotorsports.com

Total

\$9,722.39



BLUE MASERATI GH13L1

FOR 1969

Invoice

Date	Invoice #
9/22/2018	869

512 Main Street Westbury, NY 11590 516-334-1234

Bill To

Dennis Tselentis

Year

1973

Make

Maserati

Model

Ghibli

License

Color

Blue

VIN#

Mileage

Claim#

Item	Qty	Description	Rate	Amount
Labor \$85.00	16	-Dry sand Laquer clearcoat with 2000 grit on entire car to remove defects and water spot damage in clear coat, then compound and polish entire car to make	85.00	1,360.00T
		shineApply carnauba wax to all surfaces including chrome, clean wheels, tires, glass all trim and moldings for delivery.		
Misc.	1	Send car on flatbed back to Deluxe Car Storage Sales Tax	150.00 8.625%	150.00T 130.24
		PD # 185		
		Payments/Credits		\$0.00
		Total		\$1,640.24



AutoMat Customizing & Restoration • 69 Hazel St • Hicksville, New York 11801 USA • (516)938-7373 • Fax: (516)931-8438 • autointeriors@optonline.net •

Ship To:	Bill To:	Order Numbe
Dennis Tselentis	Dennis Tselentis	20694.1
56 Harvard St. Garden City, NY 11530	Dennis Tselentis 56 Harvard St.	Order Date
USA	Garden City, NY 11530	7/8/2020
	USA	Job Number
Cell 516-318-2149		WB28048
Phone:	Phone:	

ContactIE) Year	Make	Model	Terms	Ship Via	G	rand Total:
50340	1969	Maserati		30 days	Install	•	\$ 325.88
Descript	tion	general de des de la companya de la La companya de la co			Qty/Hrs	Unit Price	Extension
Interior	& Top						300.00
Deta	il Interior Only	y (labor) Detail Interio	or		1	300.00	300.00

Payments:

Pay Type M/C

Paid Date

Amount

07/08/2020

\$325.88

Payments Total:

\$325.88

Comments

Ready 7/9 left mess on voicemail

SubTotal:	\$ 300.00
Total Tax	\$ 25.88
Grand Total:	\$ 325.88
Payments Total:	325.88
Balance Due:	\$0.00



Invoice

Date Invoice #

1/31/2022

176205

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149 Year,Make,Model

1969 Maserati Ghibli Vin# AM115744

Mileage Terms

005,726

Quantity	Item	Description	Rate	Amount
		Oil Eilean	30.00	30.00
1 sp		23.113.00 Oil Filter 20W50 Valvoline Racing Oil High Zinc	12.58	176.12
14 Oi			17.69	53.07
	MA-GTQ	Castrol DOT 4 Brake Fluid LMA	3.959	49.25
12.44 Fu	.el	Fuel	35.06	35.06
1 sp	ord	6651616 Windshield Washer Pump	46.89	46.89
1 sp	ord	15689 Washer Switch	41.11	41.11
1 sp	oord	16062 Brake Light Switch	85.00	255.00
3 R-	-12	R-12 Refrigerant	1.87	1.87
1 m	nisc	1157 Bulb	1.07	1.07
12 La	abor/Hour	Change engine oil and filter. Remove distributor cap and adjust ignition points. Remove spark plugs, clean, gap, lube threads and refit. Remove all four wheels to check brakes, pads, discs and hoses (good). Remove and replace faulty brake light switch (brake lights were not working). Flush brake fluid. Remove brake fluid reservoirs (both were leaking at the threaded fitting). Remove fittings from containers, clean of rust and replace	145.00	1,740.00

Top up brake system and bleed complete brake system

Flush clutch hydraulics and bleed clutch system with new

Repair wheel cap nut stud (stud was loose & would've lost

Check all lights, wipers, washer, instrument bulbs, heater fan, heater and vent controls and repair as necessary. Remove and replace washer switch not working, remove

and replace washer pump alos not working. Top up washer bottle, clean and aim sprayers.

sealing rings. Refit containers.

the wheel nut while driving).

with new fluid.

Sales Tax (6.35%)

Total



Invoice

Date

Invoice #

1/31/2022

176205

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149 Year,Make,Model

1969 Maserati Ghibli Vin# AM115744

Mileage

Terms

005,726

Quantity Item Description Rate Amount

Repair right rear parking and brake light, remove lens check for power and ground. Replace bulb and test. Top up fuel left side fuel tank, check both right and left fuel pumps and switch (ok).

Evacuate A/C (held vacuum for 3 days). Charge A/C system and test.

Check and retorque all radiator and heater hose clamps. Run engine and check radiator fans if they are working properly (ok).

Check oil levels to gearbox and differential (ok). Check and set tire pressures.

Test drive vehicle.

Wash exterior, vacuum interior and clean glass.

Sales Tax (6.35%)

Total



Invoice

Date

Invoice #

1/31/2022

176205

Bill To

Dennis Tselentis 56 Harvard Street Garden City, Ny. 11530 Tel:516-318-2149 Year,Make,Model

1969 Maserati Ghibli Vin# AM115744

Mileage

Terms

005,726

Quantity

Item

Description

Rate

Amount

9

Sales Tax (6.35%)

\$154.20

Total

\$2,582.57

Tel: 203-327-1747 Fax: 203-327-7140 www.vantagemotorsports.com

Page 3